

Vehicle Diagnostic Report

The Report is created by **LAUNCH X431**

Repair Shop

Shop Name:EXPRESS CAR CARE
 Address:#244,19th main road sector 4 hsr layout Bangalore Bangalore Karnataka
 Zip Code:560102
 Telephone:9945098452
 Email:carspaexpresscarcare@gmail.com
 SN:979892001906
 Test Time:2023-02-02 16:17:13
 Technician Name:Kiran



Vehicle Information

Make:Tata (India)
 Odometer:38114 km
 Vehicle Software Version:V15.00
 Diagnostic Application Version:V6.00.016
 Diagnostic path:Vehicles Selection > Passenger Vehicles > TIAGO > DOMESTIC > PETROL > BS IV > XZ > Health Report



Inspection Result

EMS (Engine Management System) 3 problems exist

- | | |
|--|-----------|
| 1.P0341-02 Camshaft Position Sensor "A" Circuit Range/Performance -CGeneral Signal Failure | Memorised |
| 2.P083F-64 Clutch Pedal Switch "A" / "B" Correlation -CSignal Plausibility Failure | Temporary |
| 3.P0172-86 System Too Rich -CHigher Fuel Quantity than Required | Temporary |

IMMO (Antitheft System) 2 problems exist

- | | |
|---|-----------|
| 1.B163A-14 IMMO- Circuit Short To Ground Or Open | Temporary |
| 2.U0100-87 Lost Communication With ECM/PCM'A' - Missing Message | Temporary |

BCM (Body Control Module) 16 problems exist

- | | |
|--|-----------|
| 1.B2227-11 Left Stop Lamp Circuit - Short To Ground | Memorised |
| 2.B2227-15 Left Stop Lamp Circuit - Short To Battery Or Open Circuit | Confirmed |
| 3.B224A-11 Right Stop Lamp Circuit - Short To Ground | Temporary |
| 4.B224A-15 Right Stop Lamp Circuit - Short To Battery Or Open Circuit | Temporary |
| 5.U0100-08 Loss Of Communication With Engine Control Module- Bus Signal/ Message Failure | Memorised |
| 6.U0100-87 Lost Communication With ECM/PCM'A' - Missing Message | Memorised |
| 7.U0131-08 Lost Communication With EPAS- Message Time Out Failure | Memorised |

8.U0151-08 Lost communication with Restraints Control Module (SRS) Bus Signal Message Failure	Memorised
9.U0151-87 Lost Communication with Restraint Control module-Missing message	Memorised
10.U0155-08 Lost Communication With Instrument Panel Cluster Module-Bus Signal/ Message Failure	Temporary
11.U0155-87 Lost Communication with instrument cluster control panel(IPC) module-Missing message	Memorised
12.P2081 [6b,c4,20,81]Please Refer To Manual	Memorised
13.U1008-16 Control Module Input Power 1 Circuit Voltage Below Threshold	Temporary
14.U1009-16 Control Module Input Power 2 Circuit Voltage Below Threshold	Temporary
15.U100A-16 Control Module Input Power 3 Circuit Voltage Below Threshold	Temporary
16.U1014-09 Ignition Switch Failure	Temporary

IPC (Instrument Cluster) 7 problems exist

1.B1909-15 Fuel Level Sensor Input Short To Battery Or Open	Temporary
2.B1934-09 Set Switch Stuck Button Component Failures	Temporary
3.B1935-09 Mode Switch Stuck Button Component Failures	Temporary
4.U0100-08 Lost Communication With Ecm-Message Timeout Failure	Temporary
5.U1309-08 Lost Communication With Anti-Lock Braking System-ASBS/ESP Message Timeout Failure	Temporary
6.B1936-56 Odometer Values Missing From VICM (Immobilizer) For Learning	Temporary
7.B1937-31 Acknowledgement Missing From VICM For Learning	Temporary

HU (Head Unit Control System) 2 problems exist

1.U3000-08 Control Module - Bus Signal / Message Failure	Temporary
2.C0955 [75,9c,49,55]Please Refer To Manual	Temporary

PDC (Park Distance Control System) 1 problem exist

1.U130B-08 Lost Communication With Head Unit- HU Message Time Out Failure	Memorised
---	-----------

The following systems are OK:

- 1.ABS (Anti-Locking Braking System)
- 2.AIRBAG (Airbag Management System)
- 3.EPAS (Electronic Power Stearing)