

Issue no	Issue description	Issue Category	Issue raised Date	Current Status
1	Break making the huge sound when pressed, giving a feeling like a	Harrier Product	23-Nov-20	Resolved
2	Hard Steering	Harrier Product	23-Nov-20	Resolved
3	Hard Honk, Honk was not working	Harrier Product	23-Nov-20	Resolved
4	Android Auto not connecting	Infotainment - Android Auto	23-Nov-20	Under observation after upgrade to vR16.09
5	Call logs not appearing in Android Auto	Infotainment - Android Auto	23-Nov-20	Under observation after upgrade to vR16.09
6	Not able to make calls from Android Auto	Infotainment - Android Auto	23-Nov-20	Under observation after upgrade to vR16.09
7	Not able to pick up calls from Android Auto	Infotainment - Android Auto	23-Nov-20	Under observation after upgrade to vR16.09
8	The infotainment system is not able to connect to the Android Auto even if the phone says that the android auto is connected.	Infotainment - Android Auto	27-Dec-20	Under observation after upgrade to version 16.60
9	The keyless key alerting system not working properly. It raises beep alerts even if all the doors, lights, and engine is shut	Harrier Product	23-Nov-20	Open
10	Car is not starting as break paddle pressed alert is not read by the system. It keeps showing the message that 'press the brake to start	Harrier Product	23-Nov-20	Resolved
11	USB cable point is having a loose connection	Harrier Product	23-Nov-20	Not Accepted as an issue
12	Infotainment system hangs when I try to make a call using Android Auto.	Infotainment - Android Auto	05-Jan-21	Resolved - with a work around of selecting default calling sim
13	Steering audio control doesn't work after I try to make a call using the Android Auto	Infotainment - Android Auto	05-Jan-21	Resolved - with a work around of selecting default calling sim
14	Reverse parking sensors stop working after I try to make a call using the Android Auto	Infotainment - General	05-Jan-21	Resolved - with a work around of selecting default calling sim
15	Music system not working	Infotainment - General	08-Jan-21	Under observation after upgrade to vQ5 R15.01
16	Reverse parking video assist did not show the impact alerts, the car's turning the image etc	Infotainment - General	08-Jan-21	Under observation after upgrade to vQ5 R15.01
17	The BT audio song is not playing	Infotainment - BT Audio	12-Jan-21	Under observation after upgrade to vQ5 R15.01
18	Android auto showing error that 'Bluetooth is not connected' while making a call	Infotainment - Android Auto	16-Jan-21	Under observation after upgrade to vQ5 R15.03
19	Song is getting interrupted or stops for a second when starting the	Infotainment -	16-Jan-21	Open
20	Song is getting played with the constant breakage or distortion or interruption when the car is in motion	Infotainment - General	17-Jan-21	Under observation after upgrade to vR16.09
21	Infotainment the system is not playing songs using Bluetooth Audio	Infotainment - BT Audio	05-Feb-21	Under observation after upgrade to vQ5 R15.03
22	Not able to delete PairedDevices	Infotainment - BT Audio	19-May-21	Under Observation after changing of the buttons on 31-May-2021
23	Bluetooth performance issue - taking almost 40 seconds to connect	Infotainment - BT	02-Jul-21	Open
24	Bluetooth connection - Not able to connect another phone	Infotainment - BT	02-Jul-21	Open
25	Bluetooth Device Pairing - Not able to search phone	Infotainment - BT	02-Jul-21	Open