

Vehicle History

Registration No. : M6J11896

Total No of Visits : 5

VEHICLE INFORMATION

OWNER INFORMATION

USER INFORMATION

Reg. No : M6J11896

Customer ID : C230263511

Customer ID : C230289523

Model : XUV700 AX7 L PET
AT 7 SEATER WHT

Name : HARMILAP HOTELS PVT.
LTD.

Name : HARMILAP HOTELS PVT.
LTD.

Chassis / Serial No. : M6J11896 \$

Address. :

Address. :

Engine No. : XXXXX

Sold By : SP010871

Org. Warranty Start Dt : 16-JUL-22

Phone :

Phone :

Visit 1 Dealer Name :

Branch Name :

Repair Order No :

Repair Order Date : 19-DEC-22

Bill Date : 22-DEC-22

Service Type : SERVICE ACTION

Kilometer : 10794

Part Amount :

SA Name :

Group :

Labour Amount :

Mechanic Name :

PSF Status :

Total Amount :

Srl.	Demanded Repair / Customer Verbatim
1	D PILLAR and RR BUMPER SCREWS REPLACEMENT
2	TAIL GATE STRIKER DAMPNER REPLACEMENT
3	ADDITION OF BEADING ON ECU BODY
4	INSTALL T-BLOCK CONNECTOR ON GVV PIPE
5	DATC ECU FLASHING
6	SERVICE ACTION

Srl.	Part Number	Part Description	Quantity	Bill Type
1	0605BAA01221N	SLEEVE PROTECTION PKB CABLE	1	Warranty
2	0107AAF00150N	SEAL HEAD LAMP	2	Warranty
3	2302BW600611N	SPECIAL SCREW M6	6	Warranty
4	S1001F070011N	SPECIAL PIPE BLOCKING CONNECTION	1	Warranty
5	2304BW600590N	ECU TOP COVER ASSY	1	Warranty
6	0106CAG00261N	NUT SPECIAL INSULATOR FIRE WALL	2	Warranty
7	AW60111	Disposable Protective Cover Kit	1	Customer Paid

Srl.	Labour Code	Labour Description	Bill Type
1	0002	D PILLAR/RR BUMPER SCREWS(6) REPLACEMENT	Warranty
2	0004	TAIL GATE FUNCTION INSPECTION	Warranty

Vehicle History

Registration No. : M6J11896

Total No of Visits : 5

3	0001	ECU BRKT BEADING FITMENT	Warranty
4	1201	DATC FLASHING	Warranty
5	0012	EMS ECU COVER ADDITION	Warranty
6	0006	CANISTER INSPECTION AND R NR	Warranty
7	0005	GVV BLOCKING CONNECTION INSTALL	Warranty

Repair Order Remarks :

OBD Codes :

Pending Job (Cust Verb) in this RO

SI No	Cust Verbatim	Source	Closing Status
1	WASHING & CLEANING	System	Washing Not Required

Visit 2 Dealer Name : Branch Name :

Repair Order No : Repair Order Date : 24-NOV-22 Bill Date : 24-NOV-22
 Service Type : 2ND FREE SERVICE Kilometer : 9720 Part Amount :
 SA Name : Group : Labour Amount :
 Mechanic Name : PSF Status : Total Amount :

Srl.	Demanded Repair / Customer Verbatim
1	WASHING & CLEANING
2	2ND FREE SERVICE AT 10000 KM 0038937

Srl.	Part Number	Part Description	Quantity	Bill Type
1	EOULTRA10	MAXIMILE ULTRA 1 LTR	6	Customer Paid
2	0303BBH0001KT	OIL FILTER WITH O RING	1	Customer Paid
3	AW60084	Disposable Protective Cover	1	Customer Paid

Srl.	Labour Code	Labour Description	Bill Type
1	1010	10000 KM Service Labour	Free Service

Repair Order Remarks :

Visit 3 Dealer Name : Branch Name :

Repair Order No : Repair Order Date : 10-NOV-22 Bill Date : 10-NOV-22
 Service Type : RUNNING REPAIR Kilometer : 9301 Part Amount :
 SA Name : Group : Labour Amount :
 Mechanic Name : PSF Status : Total Amount :

Srl.	Demanded Repair / Customer Verbatim
------	-------------------------------------

Vehicle History

Registration No. : M6J11896

Total No of Visits : 5

1 REAR LHS WHEEL ARC CHANGE

Srl.	Part Number	Part Description	Quantity	Bill Type
1	2302CW600400N	CLADDING ASSY RR WHEEL ARCH LH	1	Customer Paid
2	AW60084	Disposable Protective Cover	1	Dealer FOC

Srl.	Labour Code	Labour Description	Bill Type
1	0764	CLADDING ASSY REAR WHEEL ARCH LH - R NR	Customer Paid

Repair Order Remarks :

Pending Job (Cust Verb) in this RO

SI No	Cust Verbatim	Source	Closing Status
1	WASHING & CLEANING	System	Customer Refused

Visit 4 Dealer Name : Branch Name :

Repair Order No :	Repair Order Date : 28-JUL-22	Bill Date : 28-JUL-22
Service Type : SERVICE ACTION	Kilometer : 4143	Part Amount :
SA Name :	Group :	Labour Amount :
Mechanic Name :	PSF Status :	Total Amount :

Srl.	Demanded Repair / Customer Verbatim
1	SILVER BOX FLASHING 08.01.41
2	ESCL FLASHING
3	EMS ECU FLASHING
4	SERVICE ACTIONS

Srl.	Part Number	Part Description	Quantity	Bill Type
1	0895	EMS ECU DATA FLASHING		Warranty
2	2358	ESCL FLASHING		Warranty
3	0008	SILVER BOX FLASHING		Warranty

Repair Order Remarks :

Pending Job (Cust Verb) in this RO

SI No	Cust Verbatim	Source	Closing Status
1	WASHING & CLEANING	System	Customer Refused

Visit 5 Dealer Name : Branch Name :

Repair Order No :	Repair Order Date : 18-JUL-22	Bill Date : 18-JUL-22
-------------------	-------------------------------	-----------------------

Vehicle History

Registration No. : M6J11896

Total No of Visits : 5

Service Type : 1ST FREE SERVICE	Kilometer : 3614	Part Amount :
SA Name :	Group :	Labour Amount :
Mechanic Name :	PSF Status :	Total Amount :

Srl.	Demanded Repair / Customer Verbatim
------	-------------------------------------

1	1ST FREE SERVICE AT 1000 KM
---	-----------------------------

Srl.	Part Number	Part Description	Quantity	Bill Type
------	-------------	------------------	----------	-----------

Srl.	Labour Code	Labour Description	Quantity	Bill Type
------	-------------	--------------------	----------	-----------

1	1001	1000 KM Service Labour		Free Service
---	------	------------------------	--	--------------

Repair Order Remarks :

Pending Job (Cust Verb) in this RO

SI No	Cust Verbatim	Source	Closing Status
1	WASHING & CLEANING	System	Washing Pending