## ORIGINAL FOR RECIPIENT/DUPLICATE FOR TRANSPORTER/TRIPLICATE FOR SUPPLIER

## Job Card Retail - Tax Invoice



Customer Name & Address

SUMIT A AWASTHI

State & Code :

Loyalty Card

Mobile

Invoice No.: 3/BC/24000515.

Rate

Date: 19/04/2024 15:22:46

8976167400

27-MAHARASHTRA

Fuel Trim:

PAN:

Job Card No. ; JC24000540

Job Card Date: 19/04/2024

Reg.No. :

Mileage: 78857

SA Name ; DHANANJAY RAMBHAU MANDHA SA(M): 9594974647

Model: MARUTI S-CROSS ZETA

EW Type: NA

Taxable

Amount

Chassis No.:

Last Service: 76691 (06-10-23)

Qty.

Service type: RUNNING REPAIR Place of Supply: MAHARASHTRA

Next Service Due: PMS80

Labour

Demanded Repairs-Others/Suggested Jobs

Cust GSTIN/UIN: GSTUNREGISTERED

Part Number

DD08R1

ZC06L0

INJECTION PUMP ASSY OR HIGH

PRESSURE FUEL PUMP ASSY FOR DIESEL LATHE WORK

Description

998729

998729

Batch HSN/SAC Tax

Tax Paid Amount

Labour Charges

934.56

11,800.00

Recommendations: HIGH PRESSURE PUMP REPAIRED DONE AS PER CUSTOMER DEMAND TRAIL TAKEN WITH 34 KM ALL PARAMA METER GHECK FOUND OK

For FORT POINT AUTOMOTIVE (CARS) PVT.

Authorised Sign Hory

Sub Total Amount Less Discount

Sub Total Amount

Net Bill Amount (Rounded)

CGST-@ 9% SGST @ 9%

12,734.56 0.00 1,146.11 1,146.11

15,026.78

15,027.00

Dealer GSTIN 27AACCP5360RTZT

Rupees Fifteen Thousand Twenty Seven Only

\* Unapproved fitments may affect your and vehicle safety. Kindly do not fit any unapproved fitments in your vehicle.

Licknowledge that the jobs/repairs/service carried out in my-whicle and the respective cost estimates were explained to me. I have received my vehicle after completion of all repairs being carried out to my satisfaction and I confirm that my vehicle is in good condition. I further authorize this workshop to contact me by call or sms to inform me with any other information in relation to my vehicle.

**Customer Signature** 

Mobile No.:

0.00