



Used Car Inspection Report



Used Car Inspection Report

12345 / Sample Customer Name / Jeep
Compass / Wheels Wisdom

Complete

Flagged items	0
Order ID	12345
Customer Name	Sample Customer Name
Inspection Date	31 Mar 2024
Inspection carried out by	Wheels Wisdom
Vehicle Make and Model	Jeep Compass
Fuel Type	Diesel
Vehicle Registration Number	KA 01 XX 1234
Odometer Reading (in km)	28607
Odometer tampering suspected?	No
VIN Number in RC and Vehicle matching?	Matching
Registration Number in RC and Vehicle matching?	Matching



Photo 1

Exterior Photos

Single Photo - Covering the Front Bumper, Hood and Windshield




Photo 2



Photo 3

Single Photo - Covering the Right Fender, Wheel with Tyre, and ORVM back



Photo 4



Photo 5

Single Photo - Covering the Driver Door, Window Glass and ORVM Lens



Photo 6



Photo 7

Roof - Front Half



Photo 8

Single Photo - Covering the Rear Right Door and Window Glass



Photo 9

Right Side Running Board



Photo 10



Photo 11

Single Photo - Covering the Right Quarter Panel and Wheel with Tyre



Photo 12

Roof - Rear Half



Photo 13

Single Photo - Covering the Rear Bumper, Boot and Rear Glass



Photo 14



Photo 15

Single Photo - Covering the Left Quarter Panel and Wheel with Tyre



Photo 16

Single Photo - Covering the Rear Left Door and Window Glass



Photo 17

Left Side Running Board



Photo 18



Photo 19

Single Photo - Covering the Front Passenger Door, Window Glass and ORVM Lens



Photo 20



Photo 21

Single Photo - Covering the Left Fender, Wheel with Tyre, and ORVM back



Photo 22



Photo 23

Interior photos

Driver's Door



Photo 24

Driver's Seat



Photo 25

Driver's Seatback




Photo 26

Roof - Rear Half




Photo 27

Dashboard




Photo 28




Photo 29




Photo 30

Center Console (around Gear lever and Handbrake)



Photo 31




Photo 32




Photo 33

IRVM (Inside Rear View Mirror)




Photo 34

Rear Right Passenger Door



Photo 35

Rear Seat




Photo 36

Rear Seatback




Photo 37

Is there a 3rd row?

No

Roof - Front Half




Photo 38

Rear Left Passenger Door



Photo 39

Front Passenger Door



Photo 40

Front Passenger Seat




Photo 41

Front Passenger Seatback




Photo 42

Glove Box (when open)




Photo 43

Hood & Boot interior photos

Engine Compartment (Overall)



Photo 44



Photo 45




Photo 46

Battery



Photo 47

Boot Interior (Overall)



Photo 48



Photo 49

Spare Wheel (If absent, take a picture of the place where the spare wheel is expected to be found)



Photo 50

Tool Kit (If absent, take a picture of the place where the tool kit is expected to be found)



Photo 51



Photo 52

Jack and Handle (If absent, take a picture of the place where the jack and handle are expected to be found)



Photo 53

Disclaimer

1. The following vehicle systems are NOT visually inspectable without major disassembly, and therefore cannot be inspected: Engine components inside the Engine Head, Clutch components, Gearbox, Insides of Electrical and Electronic components, Exhaust System components, and Parts concealed behind the dashboard.
2. It is not possible to give an opinion on the above components, or to predict whether these components can turn defective or wear out after the inspected vehicle is purchased.
3. This report is ONLY A POINT IN TIME snapshot of the vehicle condition. This report is valid ONLY ON THE DATE OF INSPECTION, and is not valid after this date as vehicle condition changes rapidly based on usage.
4. It is possible that changes are made to the vehicle, after inspection and before sale. The inspection report will not contain information about such changes.
5. It is possible that intermittent problems, which are not visible continuously, MAY NOT GET CAPTURED during inspection.
6. The vehicle is not tested at Highway Speeds (> 60 kmph).

Fluid leakage test

5 minute idling test for leakages

Vehicle parked over dry surface with engine idling without A/C (Upload photo of the floor under engine compartment with number plate)



Photo 54



Photo 55

Floor surface after 5 minutes of idling without A/C

No fluids dripping

Parts and Equipment Checks

Test drive: Engine - Issues found?

No

Test drive: Acceleration - Issues found?

No

Test drive: Clutch - Issues found?

No

Test drive: Any other abnormal noises?

No

Test drive: Suspension - Noises / Vibrations / Roughness indicating a problem with the suspension system?

No

Test drive: Brakes - Noises / Feedback from brakes indicating a problem with the braking system?

No

Drive mode malfunction found? (Eco / Normal / Power Modes)

No malfunction found

Fuel / Oil burning smell inside cabin?

No

Abnormal black or white smoke detected?

No

[1000273137.mp4](#)

Aftermarket modifications found in the vehicle?

No

Major accident check - Repair or Painting Detected Inside Engine Compartment?

No

Painting work done at front bumper



Photo 56



Photo 57




Photo 58



Photo 59



Photo 60



Photo 61

Accident Check - Windshield has a different manufactured date?

No

Manufacture date - 2021




Photo 62



Photo 63




Photo 64



Photo 65




Photo 66



Photo 67

Accident Check - Body Panels Alignment Not Uniform? Steering column bent?

No

Accident Check - New Sealant Applied?

No

Any wetness / oil leakage / fuel leakage in the engine compartment?

No wetness / leakage



Photo 68



Photo 69

Signs of Engine Head assembly removal?

No



Photo 70



Photo 71



Photo 72

Any wetness / oil leakage around the clutch assembly / transmission?

No wetness / leakage




Photo 73

Coolant Circulation System - Leakage / Issues with hoses?

In good condition

Any issues found in the Air Conditioning components in the engine compartment?

In good condition




Photo 74

Radiator fins and mountings

In good condition



Photo 75

Radiator fan - Noise or abnormal functioning

Working fine

[1000273103.mp4](#)

Antenna

In good condition

All 4 doors opening from outside and inside, and inside manual lock operation

In good condition

[1000273104.mp4](#)

All 4 Tyres

In good condition

All tyres Manufacture date - 2021



Photo 76



Photo 77



Photo 78




Photo 79




Photo 80

Spare tyre

In good condition



Photo 81

Tailgate (Dicky) shocks / dampers working fine?

In good condition

[1000273105.mp4](#)

Parking brake checked

In good condition

[1000273106.mp4](#)

Sun visors

In good condition



Photo 82



Photo 83

Glove box (and Utility box if equipped)

In good condition




Photo 84

Front and Rear Seat Belts

In good condition

[1000273107.mp4](#)

All seats - Forward & Backward movements, and Seatback adjustment 1000273108.mp4	In good condition
Service reminder light glowing?	No
Front exterior lights checked 1000273135.mp4	Working fine
With engine ON, any warning lights glowing in cluster?  Photo 85	Not Glowing
Engine idling speed stable? 1000273109.mp4	Stable RPM
Outside Rear View Mirrors (ORVM) - Manual / Electrical Lens adjustment and Electrical folding 1000273110.mp4	In good condition
Steering Tilt and Telescopic Adjustments 1000273111.mp4	In good condition
Steering wheel controls 1000273112.mp4	In good condition
Headlamp and Wiper combination switches working fine? 1000273113.mp4	In good condition
Cabin lights 1000273115.mp4	In good condition
Horn 1000273116.mp4	Working
Vehicle starting without abnormal noise / delayed start 1000273109.mp4	Starting normally
Gear shifting (MT) / Gear selection (AT/AMT) 1000273117.mp4	Shifting / Selection found smooth
A/C in all speeds & temperature settings	In good condition

[1000273118.mp4](#)

A/C air flow mode operation

In good condition

[1000273119.mp4](#)

A/C Cut Off Temperature (inside A/C vent)

Normal (less than or equal to 8 Degree Celsius)



Photo 86

Parking sensors

In good condition

[1000273120.mp4](#)

Reverse camera

In good condition

[1000273120.mp4](#)

Audio system - switch on test

In good condition

[1000273126.mp4](#)

Audio system - speaker outputs

In good condition

[1000273131.mp4](#)

Remote / Central locking

In good condition

[1000273133.mp4](#)

Sunroof

In good condition

[1000273127.mp4](#)

Electrically adjustable seat

In good condition

[1000273108.mp4](#)

Windows operation from individual doors

Working

[1000273132.mp4](#)

Power windows operation from the driver's door (master switch)

In good condition

[1000273128.mp4](#)

Power window child lock switch working fine?

In good condition

Front wipers and washer checked

Working

[1000273129.mp4](#)

Rear exterior lights checked

Working

[1000273136.mp4](#)

Rear wiper and washer checked

In good condition

[1000273130.mp4](#)

Hood stay and locks

In place

Engine oil level checked

High



Photo 87

Drive belt condition

In good condition




Photo 88

Battery voltage checked

In good condition

[1000273134.mp4](#)

Bulge found in the battery?

No

Battery age

Less than 4 years (Upload photo of MFG month and year / code)

Manufacture date - 2022



Photo 89

Brake fluid condition

In good condition




Photo 90

Brake fluid level

High




Photo 91

Power Steering Type

Electrical Power Steering (EPS)

Abnormal noise from EPS?

No noise observed

Coolant condition in radiator and reservoir

In good condition




Photo 92

Coolant level

High



Photo 93

Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 12



Photo 11



Photo 13



Photo 14



Photo 16



Photo 15



Photo 17



Photo 18



Photo 20



Photo 19



Photo 21



Photo 22



Photo 23



Photo 24



Photo 25



Photo 26



Photo 27



Photo 28



Photo 29




Photo 30



Photo 31



Photo 32



Photo 33



Photo 34



Photo 35



Photo 36



Photo 37



Photo 38



Photo 39



Photo 40



Photo 41



Photo 42



Photo 43



Photo 44



Photo 45



Photo 46



Photo 47




Photo 48



Photo 49



Photo 50



Photo 51



Photo 52



Photo 53



Photo 54



Photo 55



Photo 56



Photo 57



Photo 58



Photo 59



Photo 60



Photo 61



Photo 62



Photo 63



Photo 64



Photo 65



Photo 66



Photo 67




Photo 68



Photo 69




Photo 70



Photo 71



Photo 72



Photo 73




Photo 74



Photo 75



Photo 76



Photo 77



Photo 78



Photo 79



Photo 80



Photo 81



Photo 82



Photo 83



Photo 84



Photo 85



Photo 86



Photo 87



Photo 88



Photo 89




Photo 90



Photo 91



Photo 92



Photo 93

File summary

[1000273137.mp4](#)
[1000273103.mp4](#)
[1000273104.mp4](#)
[1000273105.mp4](#)
[1000273106.mp4](#)
[1000273107.mp4](#)
[1000273108.mp4](#)
[1000273135.mp4](#)
[1000273109.mp4](#)
[1000273110.mp4](#)
[1000273111.mp4](#)
[1000273112.mp4](#)
[1000273113.mp4](#)
[1000273115.mp4](#)
[1000273116.mp4](#)
[1000273109.mp4](#)
[1000273117.mp4](#)
[1000273118.mp4](#)
[1000273119.mp4](#)
[1000273120.mp4](#)
[1000273120.mp4](#)
[1000273126.mp4](#)
[1000273131.mp4](#)
[1000273133.mp4](#)
[1000273127.mp4](#)
[1000273108.mp4](#)
[1000273132.mp4](#)
[1000273128.mp4](#)
[1000273129.mp4](#)
[1000273136.mp4](#)
[1000273130.mp4](#)
[1000273134.mp4](#)